


1 Vehicle Inspection Details				
Client Vehicle Registration Number:	1234 regno	Installation Odometer Reading:	573828	
Driver Vehicle Check				
Lamps / indicators / side repeaters / stop lamps				
Reflectors / markers / warning device	es		<b>✓</b>	
Mirror / windscreen / glass condition				
Body / wings				
Oil / cooland / fluid levels			<b>✓</b>	
Seat belts			<b>✓</b>	
Load security			<b>✓</b>	
Horn / wipers / washers				
Doors				
Brakes				
Instrument panel (warning lights etc)				
Exhaust condition				
Driving controls / steering operation				
Tyre condition / wear				
Speedometer operation				
Wheels condition				
Battery condition				



27 ms Satisfactory test buffon goardfor:

<